



photo 1: Well sign. Cargo-Frian 34-27



photo 2: Facing east along the main access road towards the location. Erosion is occurring along the side of the road.



photo 3: Facing southeast towards the location. Erosion channels have developed transporting sediment off the location.



photo 4: Facing west at edge of location near the main access road. Erosion channels are shown.



photo 5: West side of the location. There is minimal vegetation and erosion is occurring.



photo 6: Southwest side of the location facing north.



photo 7: Southeast side of the location facing north. Area has minimal vegetation growth.



photo 8: Southeast side of the location facing northwest. Area around the pit has minimal vegetation growth.