



Photo 1. View of eastern portion of project area facing northward. Junk and debris have been removed from this portion of the project area.



Photo 2. View of straw wattle and straw mulch in northeastern corner of project area. These appear to be stabilizing erosion at this time.



Photo 3. View of northern portion of project area from northeastern corner facing westward. Junk and debris has been removed.



Photo 4. View of western portion of project area from southwestern edge facing northward. Junk and debris has been removed.



Photo 5. View of Canada thistle plants within interim reclamation area. These have recently been mowed.



Photo 6. View of yellow sweetclover (*Melilotus officinalis*) and mullein (*Verbascum thapsus*) growing around project facilities. These need to be controlled.