



Photo 1. View of workover operations from well pad entrance facing center.



Photo 2. View of sediment overflowing straw wattle that is contained by second wattle. This needs maintenance and needs to be monitored.



Photo 3. View of western portion of project area from northwestern corner facing southward. Brown vegetation in foreground and along slopes on right is cheatgrass (*Bromus tectorum*).



Photo 4. View of southern portion of project area from southeastern corner facing westward. Wattles appear to be properly installed and soil stockpiles are set back from edge of project area.



Photo 5. View of eastern portion of project area from southeastern corner facing northward. Cattails (*Typha* sp.), an obligate wetland species is present adjacent to the project area (right of straw wattle).



Photo 6. View of northern portion of project area. Wetland vegetation (cattails) is established adjacent to the working area.