

Inspection# 673402266

7/23/2015
Inspection 673402266



7/14/2014
Inspection 673400788



No tank label.

7/23/2015

Inspection 673402266



No tank label.

7/14/2014

Inspection 673400788



Sediment being transported
onto location through rills
which have turned into ruts
on access road.

7/23/2015
Inspection 673402266



Sediment migration onto
location via rills on access
road.

7/14/2014
Inspection 673400788



No wellhead sign.

7/23/2015

Inspection 673402266

