



Photo 1. View of dalmatian toadflax (*Linaria dalmatica*) within the southern portion of the project area.



Photo 2. View of musk thistle (*Carduus nutans*; in background and on bottom left) and dalmatian toadflax (on bottom right) within the southern portion of the project area.



Photo 3. View of area where stormwater flows have eroded a portion of the southern fill slopes on the well pad.



Photo 4. View of rill erosion and sediment deposition in western portion of project area.



Photo 5. View of deep rills and sediment deposition within the western portion of the project area.



Photo 6. View of the flowline within the northwestern portion of the project area facing northwestward. This area appears to have recently been seeded and grassy vegetation is becoming established.



Photo 7. View of cut-slope along northeastern portion of the project area. Straw matting and vegetation appear to be effective at stabilizing this slope.