



Photo 1. View of southern portion of interim reclamation area from southwestern edge facing eastward. Little vegetation is established here.



Photo 2. View from southeastern portion of project area facing center. Little vegetation is established here.



Photo 3. View of eastern portion of project area from southeast facing northward. Little vegetation is established here.



Photo 4. View of western portion of project area from southwestern corner facing northward. Good revegetation along this slope.