



Photo 1. View of southern portion of project area from southwestern corner facing eastward. Vegetation is largely comprised of rubber rabbitbrush (*Ericameria nauseosa*).



Photo 2. View from southwestern corner of well pad facing center.





Photo 3. View of western portion of project area from southwestern corner facing northward.



Photo 4. View of erosional feature forming within eastern portion of well pad.