



photo 1: Facing south towards the location. Cattle guard has not been removed.



photo 2: Facing south towards the location. Access road has not been recontored and reclaimed.



photo 3 : Facing south towards the location along the access road.



photo 4 : Facing south towards the location.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Pipe riser found at center of the location. Lat:40.288/Long:-104.637



photo 10: Dirt mound has not been recontoured and is susceptible to erosion. Debris found along the base of pile.



photo 11: Pond at the west side of the location. Metal equipment can be seen extending out of the water.



photo 12: Pipe extends between the pond and the pit at the southeast side of the location.



photo 13: Facing southwest towards the pipe and mound of dirt between the two pits.



photo 14: Pit at the southwest side of the location.



photo 15: Wooden poles remain at the southwest side of the location.



photo 16: Facing north between the two pits.