

34-10 #28-2 Pipeline Spill August 8, 2015



Figure 1. 34-10 #28-2 pipeline spill path. The entire spill path is in the photograph.



Figure 2. Valve can with the gas eliminator that failed causing 6 bbls to leak into the borrow ditch.



Figure 3. Standing at the spill origin looking down the spill path. The yellow barrier is protecting the valve can.



Figure 4. Spill origin sample adjacent to the valve can.



Figure 5. Spill mid sample point.



Figure 6. Spill terminus sample point.



Figure 7. Straw wattles placed at the terminus of the spill path. Looking up the spill path.



Figure 8. Straw wattles placed at the terminus of the spill path. Looking down the spill path.