



OVERVIEW OF WELL PAD AND EQUIPMENT
LOOKING SOUTH



UN-BERMED 30 BBLs OPEN TOP PRODUCED
WATER TANK



OPEN GLYCOL ACCUMULATION UNDER
PUMP AT DEHYDRATOR



VEHICLE RUTTING ON SOUTH SIDE OF WELL PAD



RUN ON CONTROL BERM ON EAST SIDE WELL PAD FULL OF SEDIMENT; CUT SLOPE EROSION FORMING UNDER UNMAINTAINED BMP.



SEDIMENT MIGRATION ON TO LOCATION AT NE CORNER WELL PAD; BMPS UNMAINTAINED.



STORMWATER RUN OFF AND EROSION
FORMING ON WEST SIDE WELL PAD; ALONG
FILL SLOPE ADJACENT TO COMPRESSOR.