

Grassy Creek Coal Co 1

Inspection# 673402355

Stained soil at tank base.



Stained soil at tank base.



Tree growing in berm. Low
berm on left with vegetation.
Stained soil at tank bases.



Stained soil at wellhead.



Rills leaving location and
entering access road. Hard
hat for scale.



Sediment migration down
access road.

