

## Federal 16-2

Inspection# 675201959

Vegetation around  
equipment.



Net is sagging and there is  
vegetation in pit.





Access road has erosion and  
pipeline is exposed.

