



Photo 1. View of northern portion of project area from northwestern corner facing eastward.



Photo 2. View of western portion of project area from northwestern corner facing southeastward.



Photo 3. View of stormwater BMP within eastern portion of project area that appears to be functioning properly.