

Johnson 1-28

Inspection# 673402369

No sign at wellhead.



Battery sign listing Questar as operator/emergency contact. No labels on tank.



Rill which has developed into a rut in the access road. Evidence of sediment and coarse material being transported. Hard hat for scale.



Rills in access road. Evidence of sediment and coarse material being transported.



Rill in access road. Evidence of sediment and coarse material being transported. Hard hat for scale.



Close up of rill in access road. Evidence of sediment and coarse material being transported. Hard hat for scale.



Rills transporting boulders
and smaller sediment
down access road.



Ruts in access road
transporting sediment.



Entrance to location. Road
is overgrown and rough.

