



photo 1: Main access road traveling west towards the location. Water is flowing across and eroding the road.



photo 2: Water flowing across the road has exposed a pipeline. Approx. Lat/Long: 37.09117, -104.94348.



photo 3: There may be a plugged culvert where water source is coming from.



photo 4: Main access road shows signs of erosion and rutting.



photo 5: Further up the road towards the west the water from stream is running down the side of the road.



photo 6: Culvert at this point may be partially filled with sediment. Approx. Lat/Long: 37.089,-104.954.



photo 7: Facing west near the location. The main access road shows signs of erosion and vehicle rutting.



photo 8: Well sign, Apache Canyon 14-01



Photo 9: The lid on this cellar near the engine compressor was open and appears to be damaged..



photo 10: Southwest corner of the location facing northeast.