



Photo 1. View of erosion at culvert outlet facing toward access road at entrance. Erosional channels are approximately 1 to 2 feet wide and deep.



Photo 2. View of culvert and diversion that is full of sediment and not large enough for capacity. It appears that stormwater flows circumvent the culvert here and flow over the road, eroding the fill slope at the culvert outlet shown in Photo 1.



Photo 3. View of headcut that is approximately 2 to 4 feet wide and deep, within the eastern portion of the project area.



Photo 4. View of unused pipe material on the eastern edge of the working area.



Photo 5. View of poor revegetation in the western portion of the project area. This should be monitored and re-seeded if needed.



Photo 6. View from southeastern corner of well pad facing center. Revegetation is progressing within the eastern portion of the project area.