



Photo 1. View from northeastern corner of project area facing center. Grasses such as smooth brome (*Bromus inermis*) and dropseed (*Sporobolus* sp.) are established here.



Photo 2. View of eastern portion of project area from northeastern corner facing southward.



Photo 3. View of western portion of project area from northwestern corner facing southward. Vegetation on slopes and flat surface appear to be effectively stabilizing the cut-slope.



Photo 4. View of stormwater erosion occurring around project facilities in the eastern portion of the project area. This should be stabilized.