



Photo 1. View of musk thistles (*Carduus nutans*) within the interim reclamation area.



Photo 2. View of gaps in revegetation (foreground), what appears to be sediment transported outside of the project area (mid-ground), and irrigation canal adjacent to project area (background).



Photo 3. View of erosional channels approximately 18 inches wide and deep formed between vegetation gaps within northern portion of the project area.



Photo 4. View of erosional channels in northern portion of project area flowing toward irrigation canal in background.