



Photo 1. View of western portion of project area from southwestern corner facing northward. Straw mulch and young grass plants are present in this area.





Photo 2. Birdseye view of revegetation within western portion of project area where young grass plants are starting to become established.





Photo 3. View of eastern portion of project area from southeastern corner facing northward.



Photo 4. View of northern portion of project area from northeastern corner facing westward. Little successful germination present. This area should be monitored and re-seeded if necessary.