

Reference Area Photographs

Inspection Conducted on August 20, 2015

**Linn Energy (Linn Operating Inc)
SCHOOL POINT OM K15 696 Pad
Location Facility ID # 335991
Pit facility ID #415486**

Linn Energy K15 696 Pad



Signs at the entrance. Emergency information and site identification



Pit in process of closure. Liner has been removed. No staining was observed at the bottom or on the walls.

Linn Energy K15 696 Pad



Stockpiles / Land Treatment Cells. Looking west



Stockpiles / Land Treatment Cells. Looking north.
Piping that will not be used should be removed.

Linn Energy K15 696 Pad



Treatment cells are bermed but not lined.



Treated soil in Windrows 6 feet or higher. According to Linn Energy representatives, this soil is moved about twice a year to improve remediation. Fertilized or other additive may be incorporated to the soil.