



Photo 1. View of eastern portion of project area from northeastern corner facing southward.



Photo 2. View of well pad from northeastern corner facing center.



Photo 3. View northern portion of project area with stockpiled construction material facing westward from northeastern corner.



Photo 4. View of erosion occurring along eastern edge of the access road. Incision from high energy flows is observable between wattles and sediment accumulation above and around wattles is apparent in foreground.