



Photo 1. View of culvert outlet downstream of project area. No significant stormwater erosion is occurring here at this time.



Photo 2. View of topsoil stockpile in northern portion of project area. Straw wattles present along northern edge. No stormwater controls for topsoil on well pad side. If interim reclamation isn't completed within the next month, then the entire topsoil stockpile will need stabilization.





Photo 3. View of hole in well pad surface approximately 8 inches wide and 18 inches deep, that needs repair.



Photo 4. View of western edge of well pad from southwestern corner facing northward.





Photo 5. View of eastern edge of project area from northeastern corner facing southward.