



Photo 1. View of dense population of musk thistle (*Carduus nutans*) in eastern portion of project area.





Photo 2. View of southern portion of project area from southwestern corner facing eastward. Vegetation in this area is largely comprised of Russian knapweed (*Acroptilon repens*). It appears that the Russian knapweed was mowed or grazed during the current growing season as few flower heads are present.



Photo 3. View of Russian knapweed plants growing within the eastern portion of the project area.





Photo 4. View of erosional channel that appears to be stabilized at this time, within the eastern portion of the project area.



Photo 5. View of northern portion of project area from well pad entrance facing northwestward. A stream (likely irrigation ditch) flows adjacent to northern edge of project area.





Photo 6. View of revegetation becoming established within the teardrop of the well pad, from the northern portion facing southward.