



Photo 1. View of Russian knapweed (*Acroptilon repens*) in northern portion of project area from well pad facing northeastward.



Photo 2. View of eastern portion of project area from southeastern corner facing northward. Vegetation is progressing in the foreground with grasses such as intermediate wheatgrass (*Thinopyrum intermedium*). Russian knapweed infestation in mid-ground and background (grey vegetation) is likely spreading to reclaimed area and threatening revegetation efforts.



Photo 3. View of young musk thistle (*Carduus nutans*) rosettes within the interim reclamation area.



Photo 4. View of Russian knapweed infestation north of the project area.



Photo 5. View of western portion of the project area from southwestern corner facing northward. Revegetation in this portion of the project area appears to be progressing.



Photo 6. View of project area from southwestern corner facing center.



Photo 7. View of southern portion of project area from southwestern corner facing eastward. Irrigated field (on right) does not appear to have knapweed.