

Sonterra Energy 05-103-08096

Federal 1-30

Follow up inspection

September 11, 2015


by Kyle P Granahan



^ - Initial inspection

^ - Follow up inspection

Tank labels incomplete and emergency contact number not valid.



^ - Initial inspection

^ - Follow up inspection

Tank labels incomplete and emergency contact number not valid.



^ - Initial inspection

Brush and weeds inside blowdown pit, fence and stormwater BMP's around pit need maintained.



^ - Follow up inspection



^ - Initial inspection

Brush and weeds inside blowdown pit, fence and stormwater BMP's around pit need maintained.



^ - Follow up inspection

*Hard hat for visual reference



^ - Initial inspection



^ - Follow up inspection

Tank battery sign – incomplete.



^ - Initial inspection



^ - Follow up inspection

Weeds/brush within 25' of production equipment.



^ - Initial inspection
Brush/weeds within 25' of production equipment.



^ - Follow up inspection