



Photo 1. View of new cobble armoring and straw wattle in eastern portion of project area from well pad facing upstream.



Photo 2. View of upper portion of new cobble armoring within erosional channel from eastern edge of project area facing downstream (toward well pad).



Photo 3. View of musk thistle (*Carduus nutans*) within the project area that appears to have been treated.



Photo 4. View of numerous small musk thistle rosettes within the southern portion of the project area.