



Photo 1. View of diversion channel in southern portion of project area, from southern edge of well pad facing westward. This should be monitored and BMPs applied if down-cutting worsens.





Photo 2. View of shallow erosional feature within western portion of project area. Small gravel/cobble has been placed here. This needs monitoring to make sure it does not worsen.





Photo 3. View of shallow erosional feature within eastern portion of the project area.



Photo 4. View of project area from eastern corner facing center. Short grasses such as smooth brome (*Bromus inermis*) and dropseed (*Sporobolus* sp.) are growing in the foreground.





Photo 5. View of southeastern portion of project area from eastern corner facing southwestward.



Photo 6. View of northwestern portion of project area from northern corner facing southwestward.