




Photo#1: View of location to SW corner ; close up depicted in next photo. Visible Ponding water



Photo#2: SW corner of location, erosion and reclamation failure evident



Photo#3: South side of Location; sign defining reclamation area in following photos. Obvious Stormwater run-on.



Photo#4: Interim Reclamation; It appears that Last seeding/reclamation activity was not completed along the slope contour. This shows lack of BMPs being utilized, potentially increasing erosion issues.



Photo#5: Kochia establishment in Interim Reclamation area east of Photo #4. No evidence of the required perennial vegetation establishment.



Photo#6: View from NE corner , South to close up in following photo. Obvious ponding and erosion run-on.



Photo#7: SE corner of Location, failure of vegetation and erosion evident.



Photo#8: Channel erosion from NW corner of Location to center ponded area.



Photo#9: Erosion/Soil migration from NE corner to center ponding area. No perennial stabilizing vegetation.