



Photo#1: Entering Location, facing West.



Photo#2: View of Location berms facing SW.



Photo#3: View of berms on North side of location, looking East.



Photo#4: Close up of failed establishment of perennial vegetation.



Photo#5: Erosion on unstabilized berms.