

**Federal 6-25**

Inspection# 673402474

Rills leaving location.

Inspection 673402474  
9/24/2015



Rills leaving location.

Inspection 673401912  
3/17/2015



Rills leaving location.

Inspection 673402474  
9/24/2015



Erosion gully on west  
side of location.

Inspection 673402474  
9/24/2015



Erosion gully on west side  
of location.

Inspection 673401912  
3/17/2015



Erosion gully on west side  
of location. Hard hat for  
scale.

Inspection 673402474  
9/24/2015



Erosion gully on west side  
of location. Evidence of  
sediment migration.

Inspection 673401912  
3/17/2015



Erosion gully on west side  
of location. Evidence of  
sediment migration.

Inspection 673402474  
9/24/2015



Erosion gully on west side of location. Evidence of sediment migration all the way to drainage in background.

Inspection 673402474  
9/24/2015



Erosion gully on west side of location. Evidence of sediment migration all the way to drainage in background.

Inspection 673401912  
3/17/2015



Erosion gully on west side  
of location next to old  
tank battery berm.

Inspection 673402474  
9/24/2015



Erosion rill on access road.

Inspection 673402474  
9/24/2015



Erosion rill on access  
road.

Inspection 673401912  
3/17/2015

