

PETROHUNTER OPERATING  
COMPANY - 10200

LAKE #16-21

API # 05-103-10973

10/02/2015



A1

Missing emergency contact number and  
nearest public access road



2014.10.22 08:50



2015.10.02 13:29



A2



Pit liner at entrance of location

2014.10.22 08:51

← Initial inspection

Follow up inspection →



2015.10.02 13:30





A3



Trash and unused equipment on location







Trash/debris on follow up inspection







A4



Pit liner scattered through  
out recent pit reclaim







Follow up inspection – pit liner in pit reclaim





Joint of casing on location

A5









A7

Wellhead TA with 2450psi,  
missing wellhead sign



2014.10.22 09:05



2015.10.02 13:16