

Jones 1-11

Inspection# 673402480

Vegetation growing on
berm. (2 of 4) stained soil
spots at tank base.

9/25/2015

Inspection 673402480



Close up of (2 of 4) stained
soil spots from previous
picture.

9/25/2015

Inspection 673402480



(3 of 4) Stained soil spot at tank base.

9/25/2015

Inspection 673402480



(4 of 4) stained soil spot at tank base.

9/25/2015

Inspection 673402480



Close up of (4 of 4) stained soil spot at tank base.

9/25/2015

Inspection 673402480



Stained soil at flowline.

9/25/2015

Inspection 673402480



Vegetation growing in
separator berm.

9/25/2015

Inspection 673402480



Stained soil at tank base.

9/25/2015

Inspection 673402480



Stained soil at tank base.

9/25/2015

Inspection 673402480



Slow drip leak at loadout.

9/25/2015

Inspection 673402480



Ruts in access road.
Sediment migration.
Hard hat for scale.

9/25/2015
Inspection 673402480



Sediment migration down
rills on access road.

9/25/2015
Inspection 673402480

