

Elk Springs Unit 1

Inspection# 673402518

Overgrown location.

9/30/2015

Inspection 673402518



Rills in access road. Appears to have been graded since previous inspection.

9/30/2015

Inspection 673402518



Rill in access road.

4/6/2015

Inspection 673401982



Rills in road. Sediment migration apparent.

9/30/2015

Inspection 673402518



Rills in road. Sediment migration apparent.

4/6/2015

Inspection 673401982

