



Photo 1. View of project area from well pad entrance facing northward. Pooled water does not appear to be causing rutting or vehicle diversion. Road is graveled. Also see photo 2.



Photo 2. View of puddle in “teardrop” portion of project area. Landowner access is in background (on right and does not cross puddle area).



Photo 3. View of revegetation within teardrop area. Grasses such as blue grama (*Bouteloua gracilis*) and western wheatgrass (*Pascopyrum smithii*) are becoming established. Kochia (*Kochia scoparia*) and Russian thistle (*Salsola tragus*)-most less than 1 foot tall, are also present.



Photo 4. Typical birdseye view of revegetation within the teardrop area. Blue grama and Russian thistle are growing here.



Photo 5. View of western portion of project area from northwest edge of working area facing southward. Revegetation appears to be progressing here.



Photo 6. View of eastern portion of project area from northeastern corner facing southward. Smooth brome (*Bromus inermis*) and antelope bitterbrush (*Purshia tridentata*) are well established.



Photo 7. View of trailer and what appears to be other landowner debris being stored at southwestern portion of project area.