



Photo 1. View of western portion of project area from northwestern corner facing southward. Revegetation is progressing in this area.



Photo 2. View of northern portion of project area from northwestern corner facing eastward.





Photo 3. View of cobble BMP in southwestern corner of project area.





Photo 4. View of cobble BMPs and diversion filling with sediment along southern edge of working area.





Photo 5. View of eastern edge of working area facing northward. Diversion is filling with sediment.