



Photo 1. View of well sign at well pad entrance that is tipped over.



Photo 2. View of erosional channel at well pad entrance flowing across well pad toward the northern edge. Channel is approximately 1.5 feet wide and deep.





Photo 3. View of area where erosional channel in Photo 2, flows off of the northern edge of the working area.



Photo 4. View of what appears to be surface owner equipment within northern portion of project area.





Photo 5. View of well pad from southern edge facing northward toward center.