



photo 1: Well sign, Pumpernickel 14-29



photo 2: Southwest corner facing northeast.



photo 3: Southwest side of pad has minimal vegetation cover.



photo 4: An erosional channel has developed off the east side of the pad.



photo 5: Erosional channel has developed off the east side of the pad.



photo 6: Side of the access road is not well stabilized.