



photo 1: Facing north towards the access road off of main road.



photo 2: Access road towards the location has not been reclaimed and culverts remain in place.



photo 3: Facing east along access road. Access road is eroding around the culvert.



photo 4: Access road is eroding around the culvert.



photo 5: Facing east along access road. Erosion is occurring on and along the side of the access road.



photo 6: Erosion is occurring across the road which is making the road inaccessible.



photo 7: Facing east towards the location.



photo 8: Erosion occurring along the access road near the location.



photo 9: North side of the location facing south.



photo 10: Northeast corner of the location facing southwest.



photo 11: Center of the location facing southwest. Erosion occurring along west side of the pad.



photo 12: Erosion channels at the southwest corner of the location.



photo 13: Southwest corner of the location facing north.



photo 14: Sediment trap the the southeast corner of location is filled with sediment.



photo 15: East side of the pad. Erosion channel is transporting sediment off the location.



photo 16: Northeast corner of the location facing southwest. Sediment trap is filled with sediment.