



photo 1: Well sign, Drowsey Duck 43-30



photo 2: Facing west. Erosion occurring along the access road near the location.



**photo 3:** Facing southwest. Erosion occurring along the access road near the location.



**photo 4:** East side of the location facing south. Erosion channel developing on the pad.



photo 5: Sediment trap at the northeast corner of location is filling up with sediment.



photo 6: South side of the location facing north.