

Wilson Ranch
12N-27HZ



Photo 1. Photo taken from southern location of facility pad, facing Northeast.

Wilson Ranch
12N-27HZ



Photo 2. Photo taken from southern location of facility pad, facing North towards topsoil stockpile.

Wilson Ranch
12N-27HZ



Photo 3. Photo taken from southern location of facility pad, facing Northwest.

Wilson Ranch
12N-27HZ



Photo 4. Photo taken from northern location of well pad, facing Southeast.

Wilson Ranch
12N-27HZ



Photo 5. Photo taken from northern location of well pad, facing South.

Wilson Ranch
12N-27HZ



Photo 6. Photo taken from northern location of well pad, facing Southwest.

Wilson Ranch
12N-27HZ



Photo 7. Photo taken of topsoil stockpile from western location of facility pad, facing South.

Wilson Ranch
12N-27HZ



Photo 8. Photo taken of topsoil stockpile from northern location of facility pad, facing East.

Wilson Ranch
12N-27HZ



Photo 9. Photo taken from western edge of facility pad, facing south. Stormwater control ditch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 10. Photo taken from southwest location of facility pad, facing West. Stormwater sediment catch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 11. Photo taken from southwest location of facility pad, facing Northeast. Stormwater sediment catch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 12. Photo taken from southwest location of facility pad, facing West. Stormwater control ditch located in center of photo heading West from sediment catch.

Wilson Ranch
12N-27HZ



Photo 13. Photo taken from western location of facility pad and well pad, facing South. Stormwater control ditch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 14. Photo taken from northwest location of facility pad, facing North. Stormwater sediment catch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 15. Photo taken from northwest location of facility pad, facing East towards north topsoil stockpile. Stormwater sediment catch located in center of photo.

Wilson Ranch
12N-27HZ



Photo 16. Photo taken from northwest location of facility pad, facing West. Stormwater control ditch located in center of photo.

Wilson Ranch
12N-27HZ




Photo 17. Photo taken from eastern edge of facility pad and well pad, facing North. Stormwater control ditch, culvert, and straw wattle in center of photo for access road.