



Photo 1. View of eastern portion of project area from well pad entrance (northeast) facing southward. Russian thistle (*Salsola tragus*) plants are growing along the edges of the working area and facilities areas and needs to be removed.





Photo 2. View of Russian thistle plants growing along the eastern edge of the project area (brown spiny vegetation on right side of photo).





Photo 3. View of Russian thistle debris (in background) that appears to have blown off of the project area caught along the fenceline, just east of the project area.



Photo 3. View of erosional channel (approximately 2 feet wide and 6 inches deep) forming within the northeastern portion of the project area.





Photo 4. View of southern portion of the project area from the southeastern portion of the project area facing westward. Revegetation is comprised of both desirable and undesirable species such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and alyssum (*Allysum simplex*).



Photo 5. View of western portion of the project area from the northwestern corner facing southward.