

## Silverback 36-A




**Photo 1.** Photo taken from northern access road with no stormwater BMP's, facing East on 10/20/2015.

## Silverback 36-A



**Photo 2.** Photo taken from northern location, facing West on 10/20/2015. No stormwater control BMPs.

## Silverback 36-A



**Photo 3.** Photo taken from northern access road with no stormwater BMP's, facing East on 10/23/2015. Corrective action was not met.

## Silverback 36-A



**Photo 4.** Close-up photo taken from northern access road with no stormwater BMP's, facing East on 10/23/2015. Also, the County road bar ditch disturbance is exceeding the permitted area. This will be forwarded onto OGLA for further review.

## Silverback 36-A



**Photo 5.** Close-up photo taken from northern location, facing West on 10/23/2015. No stormwater control BMPs. Corrective action was not met.

## Silverback 36-A



**Photo 6.** Photo taken from northern location, facing West on 10/23/2015. No stormwater control BMPs. Corrective action was not met.

## Silverback 36-A



**Photo 7.** Photo taken from west location, facing South on 10/23/2015. No stormwater control BMPs. Corrective action was not met.

## Silverback 36-A




**Photo 8.** Photo taken from southern location, facing East on 10/23/2015. Stormwater control ditch about 30 feet south of disturbed location.

## Silverback 36-A



**Photo 9.** Photo taken from Southeast corner of location, facing North towards topsoil stockpile on 10/23/2015. No stormwater controls. Also, pooling water in center of photo. Corrective action was not met.

## Silverback 36-A



**Photo 10.** Photo taken from northeast location of the east stormwater control ditch, facing South on 10/20/2015. Dozer operator installed ditched after discussing lack of BMPs on 10/20/2015.

## Silverback 36-A



**Photo 11.** Photo taken from east location, facing North on 10/23/2015. Topsoil stockpile was placed on top of east stormwater control ditch (refer to Photo 10). Need to reconstruct stormwater control ditch and stormwater controls need to be in place for the topsoil stockpile.