



Photo 1. View of eastern portion of project area from southeastern corner facing northward. A significant quantity of junk and debris is being stored here.





Photo 2. View of junk and debris in southern portion of the project area. Some appears like it could be oil and gas related, as evidenced by metal pipes, and steel anchor cable.





Photo 3. View of project area from southeastern corner facing center. A road is present around the perimeter of the location.



Photo 4. View of Russian knapweed (*Acroptilon repens*) and kochia (*Kochia scoparia*) plants within the southern portion of the project area.





Photo 5. View of actively growing Russian knapweed plants growing within the project area.





Photo 6. View of area where vegetation was recently scraped within central portion of project area. Area is approximately 50 feet wide and 50 feet long.





Photo 7. View of pile of kochia debris that is approximately 6 feet tall and 10 feet wide, within central portion of the project area.





Photo 8. View of eastern portion of working area where it appears revegetation is progressing, with western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and yellow sweetclover (*Melilotus officinalis*).