



**Photo 1:** Photo taken from access road west of location, facing east. Storm water erosion evident on road. Darker vegetation to right of well is Scotch thistle (please see photos 3 and 4).



**Photo 2:** Photo of PR well Murphy # 11-5, API # 005-07112



**Photo 3:** Photo from South end of well location, facing south. Note the abundance of Scotch thistle on site, these are noxious weeds and must be managed. Note the development of rill erosion on slope.



**Photo 4:** Photo from South end of location, facing South. Note the abundance of Scotch thistle on site, these are noxious weeds and must be managed. Note the development of rill erosion on slope.



**Photo 5:** Photo of Guy line anchor. Guy line anchors need to be clearly marked/identified.



Photo 6: Photo of Murphy # 11-5 tank batteries. Battery location is approximately one quarter (1/4) of a mile east of well location.



**Photo 7:** Photo taken from battery location facing west. Note the rill erosion developing on site.



**Photo 8:** Photo taken from battery location facing west. Note the rill erosion developing on site.



**Photo 9:** Photo taken from Southwest side of battery location, facing North. Note the Scotch thistle; this is a noxious weed and must be managed.