



Photo 1: Photo of entrance sign on North side of location. Not the vegetative debris along fence line.



Photo 2: Photo taken from North side of location looking east. Note the trash debris in center of photo.



Photo 3: Photo taken from North side of location looking west. Interim reclamation in progress.



Photo 4: Photo taken from North side of location looking south. Photo of Kochia and Russian thistle weeds along center of storm water control ditch.



Photo 5: Photo taken on South end of location facing south. Note the vegetative debris center of photo (arrow in red), and Russian thistle/Kochia weeds towards top of photo (arrow in yellow).



Photo 6: Photo from Southeast portion of location. Photo of rill erosion on slope.



Photo 7: Photo taken from Southeast side of location facing north. Interim reclamation in progress.



Photo 8: Photo taken from Southeast of location facing west. Interim reclamation in progress.



Photo 9: Photo taken from South side of location. Trash and weed debris in fence line.



Photo 10: Photo taken from Southern end of location facing north. Interim reclamation in progress.



Photo 11: Photo taken from Southern end of location facing northwest. Interim reclamation in progress.



Photo 12: Photo taken from west end of location. Photo of rill erosion on slope.



Photo 13: Photo of well pump. Note the weed debris among containers.