



Photo 1: Photo of pump jack sign.



Photo 2: Photo taken from south end of location facing north. Photo of reclamation in progress.



Photo 3: Photo of reclamation in progress.



Photo 4: Photo taken on northeast of location. Photo of rill erosion and Russian thistle weed debris.



Photo 5: Photo taken on northeast of location. Photo of rill erosion and Russian thistle weed debris.



Photo 6: Photo taken on northeast of location. Photo of rill erosion and Russian thistle weed debris.



Photo 7: Photo taken on northeast of location facing south. Photo of reclamation in progress.



Photo 8: Photo taken from northwest of location facing east. Note the Russian thistle weed debris.



Photo 9: Photo taken on southern end of location. Note the weed debris in equipment.