



**Photo 1.** Photo taken from southeast location, facing South. Need to install stormwater control ditch. Surface roughening is inadequate.



**Photo 2.** Photo taken from southeast location, facing Southwest. Need to install stormwater control ditch. Surface roughening is inadequate.



**Photo 3.** Photo taken from western location, facing Northwest. Need to install stormwater control ditch. Surface roughening is inadequate.



**Photo 4.** Photo taken from eastern topsoil location, facing North. Need to install stormwater control ditch around topsoil stockpile to prevent the loss of topsoil offsite.