

This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.



Photo 1. View of northern portion of project area from well pad entrance facing westward.



Photo 2. View of erosional channel (approximately 2 feet wide and 1 foot deep) and damaged anchor marker in southwestern portion of project area.





Photo 3. View of southern portion of the project area from southwestern portion facing eastward.