



Photo 1. View of stormwater diversion on southwestern edge of the working area from northwestern corner facing southward.



Photo 2. View of area where significant erosion begins within stormwater diversion in northwestern corner of working area.





Photo 3. View of area where erosional channel flows outside of fenced area and through the northern portion of the project area.



Photo 4. View of the northeastern portion of the working area from the northern corner facing southward.





Photo 5. View of the southern portion of the project area from the southeastern corner facing westward.