

Lajco



Photo 1. Photo taken of east, northern access road, facing West. Stormwater control ditch with culvert in center of photo.

Lajco



Photo 2. Photo taken of east, northern access road, facing East. Stormwater control ditch with culvert in center of photo.

Lajco



Photo 3. Photo taken of west, northern access road, facing West. Stormwater control ditch with culvert in center of photo.

Lajco



Photo 4. Photo taken of west, northern access road, facing East. Stormwater control ditch with culvert in center of photo.

Lajco



Photo 5. Photo taken of southern topsoil stockpile, facing Southwest.

Lajco



Photo 6. Photo taken of southern topsoil stockpile, facing Northwest. Need to stabilize topsoil stockpile. Topsoil salvage process was not complete during this inspection.

Lajco



Photo 7. Photo taken of northern location, facing South. Topsoil removal in process.